

U.S. Department of Homeland Security

United States Coast Guard



LOCAL NOTICE TO MARINERS

SEPTEMBER WEEKLY SUPPLEMENT

NOTICE NUMBER 37/03 September 16, 2003

NIS watchstander, 24 hours a day at (703) 313-5900

** INTERNET ADDRESS **
http://www.navcen.uscg.gov/lnm/d14/

ISSUED BY: Commander, Fourteenth Coast Guard District (oma)

PJKK Federal Building, Room 9-236 300 Ala Moana Boulevard

Honolulu, HI 96850-4982

Telephone: (808) 541-2316 Nights: (808) 541-2500 Fax: (808) 541-2309

Email: sholman@D14.uscg.mil

Navigation information having been of immediate concern to the Mariner, and promulgated by the following broadcasts, has been incorporated in this notice when still significant: ⇒ CCGD14 (D14) BNM's: 241-03 to 243-03

> COGARD MARIANAS SECTION (MARSEC) BNM's: 147-03 to 148-03

NOTES:

(1) Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution.

(2) The Local Notice to Mariners is published in its entirety once a month. The Monthly Edition should be retained as a reference for subsequently issued Weekly Supplements. The Weekly Supplements will be published in intervening weeks and will contain only new information with the exception of DISCREPANCIES-DISCREPANCIES CORRECTED section that is an accurate list maintained each week.

REFERENCES: Light List, Vol. VI, Pacific Coast and Pacific Islands, 2003 Edition (COMDTPUB P16502.6).

U.S. Coast Pilot 7, Pacific Coast: California, Oregon, Washington, and Hawaii (35th Edition).

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

I. SPECIAL NOTICES

LOCAL NOTICE TO MARINERS ON THE INTERNET

The Fourteenth District Local Notice to Mariners (LNM) is available on the World Wide Web at http://www.navcen.uscg.gov/lnm/d14/. Customers with Internet access are encouraged to take advantage of this service. The Internet delivers faster information, gives multiple copy customers the ability to print needed amounts, and provides access to archived LNM information as far back as 1995. In addition, the LNM is available via e-mail. To be added to the e-mail mailing list, send your request to SHolman@d14.uscg.mil.

DEPARTMENT OF HOMELAND SECURITY- REPORTS OF SUSPICIOUS ACTIVITIES

The Department of Homeland Security (DHS) encourages the maritime public to report information concerning suspicious activity to their local Federal Bureau of Investigation (FBI) Joint Terrorism Task Force (JTTF) office, http://www.fbi.gov/contact/fo/fo.htm, or to other appropriate authorities. Individuals can contact the DHS watch and warning unit at (202) 323-3205, toll free at 1-(888) 585-9078, or by e-mail to nip-watch@fbi.gov. The U.S. Coast Guard reminds the maritime industry that they may also report information concerning suspicious activity to the National Response Center (NRC) at 1-(800) 424-8802.

HI ISLANDS - KAHOOLAWE - ORDNANCE DETONATIONS

Planned ordnance detonations will be conducted around the island of Kahoolawe in an area bound by the following coordinates: 20-37-30N 156-32-48W, 20-34-48N 156-30-24W, 20-28-54N 156-30-24W, 20-28-06N 156-41-48W, 20-30-30N 156-44-12W, 20-33-12N 156-44-30W, 20-37-30N 156-36-24W, thence to the point of origin, effective 0800W-1700W on the following dates: September 15-20, 2003, September 22-27, 2003, and September 29, 2003 – October 04, 2003. In the interest of safety, all vessels are requested to remain clear of the area.

HI ISLANDS - OAHU - ALA WAI DEBRIS TRAP MOORING BUOY

A white and orange debris trap buoy will be added in the Ala Wai Canal near the Ala Moana Boulevard Bridge in late September/early October.

HI ISLANDS - BARBERS POINT - OFFSHORE MAINTENANCE

The offshore maintenance project at the Tesoro SPM Tanker Terminal Facility will take place from September 25, 2003 – October 06, 2003. The facility is located in the Security Zone 1.5 nautical miles off Barbers Point, Oahu, Hawaii. There will be heavy construction and towing vessel traffic in the immediate facility area, Security Zone, and transits to and from Barbers Point, Hawaii. Extensive commercial diving operations will also be conducted at this time. In the interest of safety, all vessels are requested to remain clear of the area.

II. <u>DISCREPANCIES - DISCREPANCIES CORRECTED</u>

Abbreviations normally used in the Local Notice to Mariners

BNM – Broadcast Notice to Mariners TRLB – Temporarily Replaced by Lighted Buoy LNM - Local Notice to Mariners TRUB – Temporarily Replaced by Unlighted Buoy

 $\begin{array}{ll} IMPCHA- Improper \ Characteristics & TLB- Temporary \ Lighted \ Buoy \\ TUB- Temporary \ Unlighted \ Buoy & TDBN- Temporary \ Daybeacon \end{array}$

TLT – Temporary Light INOP – Inoperative REDINT – Reduced Intensity

Shaded text denotes new discrepancy since last LNM.

DISCREPANCIES: Federal Aids:

| LLNR | Name of Aid | Status | Chart Affected (Largest Scale) | BNM Reference | LNM Reference |
|-------|--|--------------|-----------------------------------|------------------|---------------|
| 30080 | Johnston Atoll Channel Entrance Lighted Buoy 2 | MISSING | 83637 | 239-03 | 36/03 |
| 30235 | Steps Point Light | EXTINGUISHED | 83484 | 007-03 | 35/03 |

DISCREPANCIES: Private Aids:

| DISCILL | DISCREI ALVEIES. I TIVALE ALUS. | | | | | | | | | |
|---------|---|---------|-----------------|-----------|---------------|--|--|--|--|--|
| LLNR | Name of Aid | Status | Chart Affected | BNM | LNM Reference | | | | | |
| | | | (Largest Scale) | Reference | | | | | | |
| 29075 | Kaiser Boat Channel Daybeacon 2 | MISSING | 19358 | 191-03 | 29/03 | | | | | |
| 29110 | Ala Wai Boat Harbor Channel Daybeacon 3 | TRUB | 19369 | 103-02 | 33/00 | | | | | |
| 29115 | Ala Wai Boat Harbor Channel Daybeacon 4 | TRUB | 19369 | | 10/01 | | | | | |

DISCREPANCIES: FAD Buoys:

| Name of FAD | Assigned Location | Assigned Position | Status | Chart Affected (Largest Scale) | LNM Reference | | | | | |
|----------------|-----------------------|----------------------|------------------|-----------------------------------|---------------|--|--|--|--|--|
| BB | Moloaa– Kauai | 22-13-36N 159-13-54W | OFF STATION | 19381 | 37/03 | | | | | |
| FF | Pukaulua Point – Maui | 20-50-12N 155-43-54W | REPORTED MISSING | 19340 | 20/03 | | | | | |
| JJ | Kamohio – Kahoolawe | 20-24-12N 156-38-00W | REPORTED ADRIFT | 19340 | 06/03 | | | | | |
| LA | Lahaina – Maui | 20-41-00N 156-42-30W | REPORTED ADRIFT | 19347 | 13/03 | | | | | |
| LL | Hauula – Oahu | 21-44-54N 157-45-18W | REPORTED ADRIFT | 19004 | 34/03 | | | | | |
| Z | Kipukai – Kauai | 21-52-30N 159-18-30W | REPORTED ADRIFT | 19381 | 29/03 | | | | | |

DISCREPANCIES CORRECTED: Federal Aids: (None) **DISCREPANCIES CORRECTED: Private Aids:** (None) **DISCREPANCIES CORRECTED: FAD Buoys:** (None)

III. TEMPORARY CHANGES – TEMPORARY CHANGES CORRECTED (None)

IV. CHART CORRECTIONS

| AD YR | Astronomic Datum (Year) | NAD YR | North American Datum (Year) |
|--------|------------------------------|---------|-----------------------------|
| BABSAD | BAB South Astro Datum | OHD | Old Hawaiian Datum |
| LD | Local Datum | GUAM YR | Guam Datum (Togcha) |
| WGS YR | World Geodetic System (Year) | | |

Corrective action effecting charts is contained in this section. Chart Corrections are listed numerically by chart number beginning with the lowest and progressing through all charts affected. The correction listed pertains to that chart only. *It is up to the mariner to decide which charts are to be corrected.* The following example explains the individual elements of a typical correction.

| Chart Number | Chart Edition ↓ | Edition Date ↓ | Last Local Notice to Mariners | Horizontal Datum Reference ↓ | Source of Correction | | Current Local Notice to Mariners • |
|-----------------|------------------------------|-----------------------------|-------------------------------|---|----------------------|------------------|-------------------------------------|
| 19320 | 16Ed. | 12/14/1996 | LAST LNM 50/00 | WGS 84 | (CCGD 14) | | 24/02 |
| | ISLAND | OF HAWAII | | | | | |
| Char | nge | Coconut Point | Directional Light to: F | G 38ft 10M | at | 19-43-36.8 N | 155-05-10.2 W |
| ↑ | | ↑ | | | | • | ^ |
| Correctiv | e Action | Object of 0 | Corrective Action | | Position | (Degrees, minute | es, seconds and tenths) |

A chart correction followed by:

(Temp) indicates that it is temporary in nature.

P indicates that it is preliminary, and that permanent corrective action will appear in a future Local Notice to Mariners.

The letter M immediately following the chart number indicates that the correction should be applied to the metric side of the chart only.

The letter **N** preceding the current Local Notice to Mariners number indicates that the affected chart is on Limited Distribution and is normally only for use by U.S. Navy, government-owned or government chartered vessels.

Courses and bearings are given in degrees clockwise from 000° T. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles.

| 19340 | 26Ed. HI – HAW | 12/02/00 AII TO OAHU | LAST LNM 29/03 | WGS 84 | (CCGD 14) | | 37/03 |
|-------|--------------------|---------------------------|------------------------------------|-----------------------------|--------------|--------------|---------------|
| Add | | Mokapu Penins | ula WECB Light F, Fl Y | 4s 27ft "F" Priv | at | 21-27-54.7 N | 157-45-03.3 W |
| 19357 | 22Ed. HI – ISLA | 08/01/02 ND OF OAHU | LAST LNM 29/03 | WGS 84 | (CCGD 14) | | 37/03 |
| Add | | Mokapu Penins | ula WECB Light F, Fl Y | 4s 27ft "F" Priv | at | 21-27-54.7 N | 157-45-03.3 W |
| 19359 | 10Ed. HI – ISLA | 08/15/99 .ND OF OAHU - | LAST LNM 08/03 - KANEOHE BAY | WGS 84 | (CCGD 14) | | 37/03 |
| Add | | Mokapu Penins | ula WECB Light F, Fl Y | 4s 27ft "F" Priv | at | 21-27-54.7 N | 157-45-03.3 W |
| 81063 | 5Ed. COMMON | 05/26/90 NWEALTH OF T | LAST LNM 23/98 THE NORTHERN MAR | WGS 84 IANA ISLANDS ROTA | (NOS NW -695 | 57) | 37/03 |
| Add | | Note: | | | at | 14-08-34.0 N | 145-09-02.9 E |
| | | ROTA HARBO |)R | | | | |

The controlling depth for Rota Harbor is 20 feet for the center 250 feet to the first turn (for the first 685 feet) of entrance channel and 16 feet for the center 150 feet for the remaining 720 feet of the channel. There is shoaling to 9 feet at the channel edges.

Change Legend to text: (see note) at 14-08-16.6 N 145-07-47.7 E

V. <u>NEW ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION</u> (None)

VI. <u>NEW PROPOSED CHANGES IN AIDS TO NAVIGATION</u> (None)

VII. GENERAL

OAHU - KANEOHE BAY - MARINE CORPS BASE HAWAII - ULUPAU CRATER WEAPONS RANGE SCHEDULE

Whenever tactical weapons firing is scheduled and in progress during daylight hours, a single large red rectangular warning flag will be flown at the two separate locations on the shore. Whenever any weapons firing is scheduled an in progress during hours of darkness, flashing red warning beacons will be displayed on the shore at Ulupau Crater. Boaters will have complete access to the danger zone whenever there is no weapons firing scheduled, which will be indicated by the absence of any warning flags, pennants, or beacons displayed ashore.

The danger zone is not considered safe for boaters whenever hazardous weapons' firing is in progress. Boaters shall expeditiously vacate the danger zone at best speed and by the most direct route. Passage of vessels through the danger zone when hazardous weapons firing is in progress will be permitted, but boaters shall proceed directly through the area at best speed. Whenever a boater disregards the publicized warning signals that hazardous weapons firing is scheduled, the boater will be personally requested to expeditiously vacate the danger zone by MCAS Kaneohe Bay military personnel utilizing a bull-horn from either a Marine helicopter or Navy crash boat.

(All times are local)

| | SUN. | MON. | TUE. | WED. | THURS. | FRI. | SAT. |
|------------------|-----------|-------------|-------------|-------------|-------------|-------------|-----------|
| Sept 14 - 20 | No Firing | 0700 - 1630 | 0700 - 1630 | 0700 - 1630 | 0700 - 1630 | 0700 - 1630 | No Firing |
| Sept 21 - 27 | No Firing | 0700 - 1630 | 0700 - 1630 | 0700 - 1630 | 0700 - 2200 | 0700 - 1630 | No Firing |
| Sept 28 – Oct 04 | No Firing | No Firing | No Firing | 0600 - 2200 | No Firing | No Firing | No Firing |

MARINE EVENTS:

The following marine events are of interest to mariners. All mariners are cautioned that event areas warrant prudent seamanship and that all Federal, State and Local regulations apply.

Sponsors and organizers frequently set up event areas prior to the actual activity. Additionally, post event clean-ups may be required. Mariners are urged to exercise caution in and around event areas prior to and after the published event times.

| Event and Location | Date | Activity | Sponsor |
|---|--------------------|---------------|--|
| HYC FRIDAY NIGHT RACE | September 19, 2003 | Sailboat Race | Hawaii Yacht Club |
| Ala Wai Harbor to Mamala Bay & return, Oahu | 5:00PM - 8:00PM | | |
| HILTON HAWAIIAN VILLAGE FIREWORKS | September 19, 2003 | Fireworks | Hawaii Explosives & Pyrotechnics, Inc. |
| DISPLAY | 8:00PM - 8:35PM | | |
| Waikiki, Oahu | | | |
| HYC FRIDAY NIGHT RACE | September 26, 2003 | Sailboat Race | Hawaii Yacht Club |
| Ala Wai Harbor to Mamala Bay & return, Oahu | 5:00PM - 8:00PM | | |
| HILTON HAWAIIAN VILLAGE FIREWORKS | September 26, 2003 | Fireworks | Hawaii Explosives & Pyrotechnics, Inc. |
| DISPLAY | 8:00PM - 8:35PM | | |
| Waikiki, Oahu | | | |
| MBYC INSHORE | September 27, 2003 | Sailboat Race | Maui Boat & Yacht Club |
| Off Puamana, Lahaina | 10:00AM - 4:00PM | | |

VIII. CORRECTIONS TO LIGHT LIST VOLUME VI: PACIFIC COAST AND PACIFIC ISLANDS 2003

| (1) Number | (2) Name and Location | (3) Position | (4) Characteristi c | (5) Height | (6) Range | (7) Structure | (8) Remarks | LNM |
|---------------|----------------------------------|---------------------------|---------------------------|---------------|--------------|----------------------|----------------|-------|
| 28675.1 | MOKAPU PENINSULA WECB LIGHT F | 21 27 55 N 157 45 03 W | Fl Y 4s | 27 | | Yellow steel tripod. | Private aid. | 37/03 |
| * | * | * | * | * | | * | * | |

IX. ADDITIONAL ENCLOSURES

Enclosure (1) U.S. Coast Pilot 7, Pacific Coast: California, Oregon, Washington, and Hawaii, 2002 (35th) Edition, Change No. 10 Enclosure (1) U.S. Coast Pilot 7, Pacific Coast: California, Oregon, Washington, and Hawaii, 2002 (35th) Edition, Change No. 11

END OF CCGD 14 LOCAL NOTICE TO MARINERS NO. 37/03

C. D. WURSTER Rear Admiral, U. S. Coast Guard Commander, Fourteenth Coast Guard District Publication-National Ocean Service-U.S. Coast Pilot 7, Pacific Coast: California, Oregon, Washington, Hawaii, and Pacific Islands, 2003 (35^{th}) Edition. Change No. 10.

Coast Pilot 7 35th 2003

Corrections

Page 163-Paragraphs 2532-2533, read:

- (6) Knows the speed and direction of the current, set, drift, and tidal state for the area to be transited;
- (7) Proceeds at a safe speed taking into account the weather, visibility, density of traffic, draft of tow, possibility of wake damage, speed and direction of the current, and local speed-limits; and
- (8) Monitors the voyage plan required by \$164.80.

(CL 879/03; FR 04/29/03)

Page 163-Paragraph 2534, line 4 through Paragraph 2535, line 1; read:

are entered in the log or other record carried on board.

\$164.80 Tests, inspections, and voyage planning.

(a) The owner, master, or operator of each towing ...
(FR 4/29/03; CL 879/03)

Page 163-Paragraph 2544, line 3; read:

of chafing gear; and of the winch brake, if installed.

(c) Towing vessels described in paragraphs (b) (1) through (4) of \$164.01 are exempt from the voyageplanning requirements outlined in this section. If any part of a towing vessel's intended voyage is seaward of the baseline (i.e., the shoreward boundary) of the territorial sea of the U.S., then the owner, master, or operator of the vessel, employed to tow a barge or barges, must ensure that the voyage with the barge or barges is planned, taking into account all pertinent information before the vessel embarks on the voyage. The

master must check the planned route for proximity to hazards before the voyage begins. During a voyage, if a decision is made to deviate substantially from the planned route, then the master or mate must plan the new route before deviating from the planned route. The voyage plan must follow company policy and consider the following (related requirements noted in parentheses);

- (1) Applicable information from nautical charts and publications (also see paragraph (b) of §164.72), including Coast Pilot, Coast Guard Light List, and Coast Guard Local Notice to Mariners for the port of departure, all ports of call, and the destination;
- (2) Current and forecast weather, including visibility, wind, and sea state for the port of departure, all ports of call, and the destination (also see paragraphs (a)(7) of \$164.78 and (b) of \$164.82);
- (3) Data on tides and currents for the port of departure, all ports of call, and the destination, and the river stages and forecast, if appropriate;
- (4) Forward and after drafts of the barge or barges and underkeel and vertical clearances (airgaps) for all bridges, ports, and berthing areas;
 - (5) Pre-departure checklists;
- (6) Calculated speed and
 estimated time of arrival at
 proposed waypoints;
- (7) Communication contacts at any Vessel Traffic Services, bridges, and facilities, and any port-specific requirements for VHF radio;
- (8) Any master's or operator's standing orders detailing closest points of approach, special

conditions, and critical maneuvers; and

(9) Whether the towing vessel has sufficient power to control the tow under all foreseeable circumstances.

(CL 879/03; FR 04/29/03)

Publication-National Ocean Service-U.S. Coast Pilot 7, Pacific Coast: California, Oregon, Washington, Hawaii, and Pacific Islands, 2003 (35^{th}) Edition. Change No. 11.

Coast Pilot 7 35th 2003

to

Corrections

Page 205-Paragraph 3454, insert
after:

§334.865 Naval Air Station North Island, San Diego, California, Restricted Area.

(a) The area. The waters within an area beginning at 32°42'55.0"N., 117°11'30.5"W.; to

32°42'57.0"N., 117°11'22.5"W.;

to 32°42'56.0"N., 117°11'19.0"W.;

 $32^{\circ}42'49.0"N., 117^{\circ}11'08.5"W.;$ to

 $32^{\circ}42'44.5"N., 117^{\circ}11'06.5"W.;$ and thence to

32°42'40.0"N., 117°11'06.5"W.

- (b) The regulation. (1) The restricted area shall not be open to swimming, fishing, water-skiing, mooring or anchorage.
- (2) Dragging, seining, other fishing operations, and other activities not under the direction of the United States, which might foul underwater installations within the restricted area, are prohibited.
- (3) All tows entering the restricted area shall be streamed and shortened to the seaward of the area and towing appendages and catenaries shall not be dragged along the bottom while proceeding through the area.
- (4) All vessels entering the restricted area shall proceed across the area by the most direct route and without unnecessary delay.
- (5) No vessel or craft of any size shall lie-to or anchor in the restricted area at any time other than other than a vessel operated by or for components, or other vessels authorized by Commander, Navy Region Southwest, or his/her

designee.

- (6) When security conditions dictate, Naval security forces may impose strict enforcement of standoff distances within the restricted area. This enforcement will not prevent utilization of navigable channels, but will serve to control its use in order to protect vital National interests.
- (c) Enforcement. The regulation in this section, promulgated by the United States Army Corps of Engineers, shall be enforced by the Commander, Navy Region Southwest, and such agencies or persons as he/she may designate.

 (FR 6/26/03)